Project Type	Project Category (Primary	Project Category (Secondary)	Application # Grantee	Asset Condition SCORE	Service Quality Impact SCORE	TECHNICAL SCORE
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	60	36	96
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10115 Bay Aging 10060 City of Petersburg	60 60	36 36	96 96
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10209 County of Loudoun	60	36	96
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10209 County of Loudoun	60	36	96
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10174 Pulaski Area Transit 10079 Town Of Blackstone/ Blackstone Area Bus System	60 60	36 36	96 96
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10079 Town Of Blackstone/ Blackstone Area Bus System	60	36	96
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10173 Charlottesville Area Transit	58	36	94
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10173 Charlottesville Area Transit 10209 County of Loudoun	58 58	36 36	94 94
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10209 County of Loudoun	58	36	94
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10209 County of Loudoun	58	36	94
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10246 Farmville Area Bus 10322 Greater Richmond Transit Company	56 56	36 36	92 92
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	56	36	92
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	56	36	92
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	56	36 36	92
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10322 Greater Richmond Transit Company 10322 Greater Richmond Transit Company	56 56	36	92 92
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	56	36	92
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	56	36	92
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10269 City of Winchester 10246 Farmville Area Bus	56 54	36 36	92 90
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10360 Greater Roanoke Transit Company	54	36	90
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	54	36	90
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	54	36	90
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10115 Bay Aging 10115 Bay Aging	54 54	36 36	90 90
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10209 County of Loudoun	54	36	90
State of Good Repair	Vehicle - Revenue vehicles	Paratransit Vehicles	10332 City of Bristol Virginia	56	33	89
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10203 District Three Public Transit	52	36	88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10203 District Three Public Transit 10203 District Three Public Transit	52 52	36 36	88 88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10203 District Three Public Transit	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10203 District Three Public Transit	52	36	88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10322 Greater Richmond Transit Company 10322 Greater Richmond Transit Company	52 52	36 36	88 88
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10322 Greater Richmond Transit Company 10322 Greater Richmond Transit Company	52 52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10322 Greater Richmond Transit Company 10322 Greater Richmond Transit Company	52 52	36 36	88 88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10322 Greater Richmond Transit Company 10322 Greater Richmond Transit Company	52 52	36 36	88 88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36 36	88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10322 Greater Richmond Transit Company 10322 Greater Richmond Transit Company	52 52	36	88 88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	52 52	36 36	88 88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10360 Greater Roanoke Transit Company 10360 Greater Roanoke Transit Company	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	52	36	88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	52 52	36 36	88 88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10275 RADAR	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10275 RADAR	52	36	88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10275 RADAR 10312 RADAR / Covington & Clifton Forge	52 52	36 36	88 88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10312 RADAR / Covington & Clifton Forge	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10115 Bay Aging	52	36	88
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10043 NVTC - City of Alexandria	52	36	88
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10173 Charlottesville Area Transit 10095 Mountain Empire Older Citizens, Inc.	52 50	36 36	88 86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10094 Danville Transit System	50	36	86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10094 Danville Transit System	50	36	86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	9961 Greene County Transit, Inc.	50	36	86
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10324 JAUNT, Inc. 10333 Hampton Roads Transit	50 50	36 36	86 86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	50	36	86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	50	36	86
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	50 50	36 36	86 86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	50	36	86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10115 Bay Aging	50	36	86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10115 Bay Aging	50	36	86
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10115 Bay Aging 10269 City of Winchester	50 50	36 36	86 86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10324 JAUNT, Inc.	50	36	86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10324 JAUNT, Inc.	50	36	86
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	9961 Greene County Transit, Inc.	50	36	86
State of Good Repair State of Good Repair	Technology - Operations Admin/Maintenance Facilities	Rider Support Hardware - Fare Collection Facility Maintenance	10094 Danville Transit System 10333 Hampton Roads Transit	60 60	25 24	85 84
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10025 AASC / Four County Transit	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10025 AASC / Four County Transit	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10025 AASC / Four County Transit	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10095 Mountain Empire Older Citizens, Inc. 10095 Mountain Empire Older Citizens, Inc.	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10095 Mountain Empire Older Citizens, Inc.	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10095 Mountain Empire Older Citizens, Inc.	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10095 Mountain Empire Older Citizens, Inc.	45	36 36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10204 Mountain Empire Older Citizens, Inc. 10095 Mountain Empire Older Citizens, Inc.	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10094 Danville Transit System	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10324 JAUNT, Inc.	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10324 JAUNT, Inc.	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10324 JAUNT, Inc. 10324 JAUNT, Inc.	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10115 Bay Aging	45	36	81

Project Type	Project Category (Primary	Project Category (Secondary)	Application # Grantee	Asset Condition SCORE	Service Quality Impact	TECHNICAL SCORE
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10324 JAUNT, Inc.	45	SCORE 36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10324 JAUNT, Inc. 10095 Mountain Empire Older Citizens, Inc.	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10272 PRTC 10272 PRTC	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10272 PRTC 10272 PRTC	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10272 PRTC 10272 PRTC	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10272 PRTC 10272 PRTC	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10272 PRTC 10272 PRTC	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRTC	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10272 PRTC 10272 PRTC	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10272 PRIC 10272 PRIC	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10025 AASC / Four County Transit	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10025 AASC / Four County Transit	45	36	81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10025 AASC / Four County Transit 10025 AASC / Four County Transit	45 45	36 36	81 81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10085 City of Harrisonburg Dept. of Public Transportation	45	36	81
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	45	36	81
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10322 Greater Richmond Transit Company 10291 Greater Lynchburg Transit Company	45 45	36 36	81 81
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10291 Greater Lynchburg Transit Company 10094 Danville Transit System	45	36 36	81 76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10094 Danville Transit System	40	36	76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10348 STAR Transit	40	36	76
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10348 STAR Transit 10122 Town of Altavista	40 40	36 36	76 76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	40	36	76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	40	36	76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	40	36	76
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10324 JAUNT, Inc. 10324 JAUNT, Inc.	40 40	36 36	76 76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10324 JAUNT, Inc.	40	36	76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10324 JAUNT, Inc.	40	36	76
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10348 STAR Transit 10324 JAUNT. Inc.	40 40	36 36	76 76
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10324 JAUNT, Inc. 10324 JAUNT, Inc.	40	36	76 76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10324 JAUNT, Inc.	40	36	76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10324 JAUNT, Inc.	40	36	76
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10025 AASC / Four County Transit 10173 Charlottesville Area Transit	40 40	36 36	76 76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	40	36	76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	40	36	76
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	40	36	76
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	40 40	36 36	76 76
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	40	36	76
State of Good Repair	Technology - Administrative	Admin Computer Hardware Purchase (Com	10072 Blacksburg Transit	60	12	72
State of Good Repair State of Good Repair	Maintenance equipment & parts Technology - Administrative	Maintenance Materials Admin Computer Hardware Purchase (Com	10246 Farmville Area Bus 10324 JAUNT. Inc.	48 60	24 12	72 72
State of Good Repair	Maintenance equipment & parts	Maintenance Materials	10046 NVTC - Fairfax County	48	24	72
State of Good Repair	Technology - Administrative	Admin Computer Hardware Purchase (Com	10272 PRTC	60	12	72
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10070 Town of Bluefield-Graham Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10070 Town of Bluefield-Graham Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35 35	36 36	71 71
		Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus				
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair					36 36 36	

Project Type	Project Category (Primary	Project Category (Secondary)	Application # Grantee	Asset Condition SCORE	Service Quality Impact	TECHNICAL SCORE
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	SCORE 36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton Roads Transit	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Roads Transit 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10246 Farmville Area Bus	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10347 Virginia Regional Transit	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10246 Farmville Area Bus	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10246 Farmville Area Bus 10333 Hampton Roads Transit	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10333 Hampton Koads Transit 10347 Virginia Regional Transit	35 35	36 36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company	35	36	71
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Replacement Bus Purchase Replacement Bus	10322 Greater Richmond Transit Company 10322 Greater Richmond Transit Company	35 35	36 36	71 71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10322 Greater Richmond Transit Company 10322 Greater Richmond Transit Company	35	36	71
State of Good Repair	Vehicle - Revenue vehicles	Purchase Support Vehicles	10046 NVTC - Fairfax County	52	18	70
State of Good Repair	Vehicle - Revenue vehicles	Expansion Bus/Vehicle	10060 City of Petersburg	40	29	69
State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Support Vehicles	10031 Williamsburg Area Transit Authority	50	18	68 68
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Support Vehicles Paratransit Vehicles	10031 Williamsburg Area Transit Authority 10333 Hampton Roads Transit	50 35	18 33	68
State of Good Repair	Technology - Operations	Software Purchase - Scheduling	10333 Hampton Roads Transit	35	33	68
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10072 Blacksburg Transit	30	36	66
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10072 Blacksburg Transit	30	36	66
State of Good Repair State of Good Repair	Technology - Administrative Vehicle - Revenue vehicles	Admin Computer Hardware Purchase (Comp Engine Replacement	10115 Bay Aging 10272 PRTC	54 30	12 36	66 66
State of Good Repair	Maintenance equipment & parts	Maintenance Materials	10322 Greater Richmond Transit Company	40	24	64
State of Good Repair	Vehicle - Revenue vehicles	Purchase Support Vehicles	10347 Virginia Regional Transit	45	18	63
State of Good Repair	Technology - Administrative	Admin Computer Hardware Purchase (Com		50	12	62
State of Good Repair	Vehicle - Revenue vehicles	Vehicle Maintenance - Overhaul	10333 Hampton Roads Transit	30	32	62
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Vehicle Maintenance - Overhaul Vehicle Maintenance - Overhaul	10333 Hampton Roads Transit 10321 NVTC - Arlington County	30 30	32 32	62 62
State of Good Repair	Vehicle - Revenue vehicles	Vehicle Maintenance - Overhaul	10046 NVTC - Fairfax County	30	32	62
State of Good Repair	Vehicle - Revenue vehicles	Vehicle Maintenance - Overhaul	10047 NVTC - VRE	30	32	62
State of Good Repair	Vehicle - Revenue vehicles	Vehicle Maintenance - Overhaul	10272 PRTC	30	32	62
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Vehicle Maintenance - Overhaul Vehicle Maintenance - Overhaul	10272 PRTC	30 30	32 32	62 62
State of Good Repair	Technology - Administrative	Admin Computer Hardware Purchase (Comp	10031 Williamsburg Area Transit Authority 10203 District Three Public Transit	50	12	62
State of Good Repair	Technology - Administrative	Admin Computer Hardware Purchase (Comp		50	12	62
State of Good Repair	Technology - Operations	Rider Support Hardware - ITS/Communicati		36	24	60
State of Good Repair	Maintenance equipment & parts	Maintenance Materials	10306 NVTC - City of Fairfax	36	24	60
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Contracting - Capital Cost Contracting - Capital Cost	10105 Central Shenandoah Planning District Commission 10105 Central Shenandoah Planning District Commission	30 30	29 29	59 59
State of Good Repair	Vehicle - Revenue vehicles	Purchase Support Vehicles	10272 PRTC	40	18	58
State of Good Repair	Vehicle - Revenue vehicles	Purchase Support Vehicles	10272 PRTC	40	18	58
State of Good Repair	Bus Shelters/Customer Facilities	Bus Shelter Installation	10321 NVTC - Arlington County	42	16	58
State of Good Repair	Bus Shelters/Customer Facilities	Bus Shelter Installation	10046 NVTC - Fairfax County	42	16	58
State of Good Repair State of Good Repair	Vehicle - Revenue vehicles Vehicle - Revenue vehicles	Purchase Support Vehicles Purchase Support Vehicles	10046 NVTC - Fairfax County 10046 NVTC - Fairfax County	40 40	18 18	58 58
State of Good Repair	Vehicle - Revenue vehicles	Purchase Support Vehicles	10046 NVTC - Fairfax County	40	18	58
State of Good Repair	System Infrastructure	Facility Maintenance	10333 Hampton Roads Transit	30	28	58
State of Good Repair	Maintenance equipment & parts	Purchase Bus Replacement Batteries	10043 NVTC - City of Alexandria	30	28	58
State of Good Repair State of Good Repair	Technology - Operations Admin/Maintenance Facilities	Operations Software - Customer Service Facility Maintenance	10072 Blacksburg Transit 10031 Williamsburg Area Transit Authority	30 30	25 24	55 54
State of Good Repair	Admin/Maintenance Facilities	Facility Maintenance Facility Maintenance	10094 Danville Transit System	30	24	54
State of Good Repair	Admin/Maintenance Facilities	Facility Maintenance	10246 Farmville Area Bus	30	24	54
State of Good Repair	Admin/Maintenance Facilities	Facility Maintenance	10324 JAUNT, Inc.	30	24	54
State of Good Repair State of Good Repair	Admin/Maintenance Facilities Admin/Maintenance Facilities	Facility Maintenance Facility Maintenance	10347 Virginia Regional Transit 10347 Virginia Regional Transit	30 30	24 24	54 54
State of Good Repair State of Good Repair	Technology - Operations	Rider Support Hardware - ITS/Communicati		30	24	54 54
State of Good Repair	Technology - Operations	Rider Support Hardware - ITS/Communicati	10094 Danville Transit System	30	24	54
State of Good Repair	Technology - Operations	Rider Support Hardware - ITS/Communicati	10272 PRTC	30	24	54
State of Good Repair	Maintenance equipment & parts	Maintenance Materials	10072 Blacksburg Transit	30	24	54
State of Good Repair State of Good Repair	Maintenance equipment & parts Maintenance equipment & parts	Maintenance Materials Maintenance Materials	10060 City of Petersburg 10269 City of Winchester	30 30	24 24	54 54
State of Good Repair	Maintenance equipment & parts	Maintenance Materials	10246 Farmville Area Bus	30	24	54
State of Good Repair	Maintenance equipment & parts	Maintenance Materials	10291 Greater Lynchburg Transit Company	30	24	54
State of Good Repair	Maintenance equipment & parts	Maintenance Materials	10324 JAUNT, Inc.	30	24	54
State of Good Repair	Maintenance equipment & parts	Maintenance Materials Maintenance Materials	10046 NVTC - Fairfax County 10348 STAR Transit	30 30	24 24	54 54
State of Good Repair State of Good Repair	Maintenance equipment & parts Admin/Maintenance Facilities	Maintenance Materials Facility Maintenance	10348 STAR Transit 10348 STAR Transit	30	24 24	54 54
State of Good Repair	Technology - Operations	Rider Support Hardware - ITS/Communicati		30	24	54
State of Good Repair	System Infrastructure	Facility Improvement	10047 NVTC - VRE	30	22	52
State of Good Repair	System Infrastructure	Facility Improvement	10047 NVTC - VRE	30	22	52
State of Good Repair State of Good Repair	System Infrastructure System Infrastructure	Facility Improvement Facility Improvement	10333 Hampton Roads Transit 10333 Hampton Roads Transit	30 30	22 22	52 52
State of Good Repair State of Good Repair	Maintenance equipment & parts	Maintenance Inspection	10333 Hampton Roads Transit 10046 NVTC - Fairfax County	30	19	52 49
State of Good Repair	Admin/Maintenance Facilities	Lease - Bus Transfer Facility	10031 Williamsburg Area Transit Authority	30	18	48
State of Good Repair	Technology - Operations	Software Purchase - On board	10115 Bay Aging	30	18	48
State of Good Repair	Vehicle - Revenue vehicles	Purchase Support Vehicles	10095 Mountain Empire Older Citizens, Inc.	30	18	48
	Bus Shelters/Customer Facilities	Wayfinding Aids - Signage	10060 City of Petersburg	30	16	46
State of Good Repair				20	16	46
State of Good Repair State of Good Repair State of Good Repair	Technology - Operations Technology - Operations	Rider Support Hardware - Safety Rider Support Hardware - Safety	10291 Greater Lynchburg Transit Company 10047 NVTC - VRE	30 30	16 16	46 46

March Control Contro	Project Type	Project Category (Primary	Project Category (Secondary)	Application # Grantee	Asset Condition SCORE	Service Quality Impact	TECHNICAL SCORE
March Carlotte March Carlotte March Carlotte March Carlotte March Carlotte March	State of Good Repair	Bus Shelters/Customer Facilities	Wayfinding Aids - Signage	10031 Williamsburg Area Transit Authority	30		
State of the Delivery Stat							
Table							
State of Control							
State of Conference Confere							
Stand Contention Standard S							
Tellings							
Store of contingers Store of contingers Store Store of contingers Store Store of contingers Store Store of contingers Store of continger							
Wide Description Property Wide Description Property							
Mage Chapman Wiles - Princes with the Chapman Mage Chapman							
Mary Expensional Works December effort Security Notice S							
Marc Education							
Mary Carlos and Carlos Mary Carlos and Carlos Mary Carlos Mary Carlos and Carlos Mary Carlos and Carlos Mary Carlos							
Maint planematical which is considered as a second of the control							
Mary California Mary Calif							
Mary Pubment Market Mark	Minor Enhancement	Vehicle - Revenue vehicles	Paratransit Vehicles	10333 Hampton Roads Transit	0	33	
Mary Selection				The state of the s			
Mary Designation Market March Market M				The state of the s			
Mary Francescone Mary France				The state of the s			
March Parlament Welch				The state of the s			
Mary Filter Programs Content of Programs Verlage				The state of the s			
Mary Friedmann Mary	Minor Enhancement	Vehicle - Revenue vehicles		10333 Hampton Roads Transit			
Mote Therement Mote The restrict which 1313 Region from Printed 0 13 13 13 13 13 13 13				The state of the s			
Mary Chargement Weble - Homew evides				The state of the s			
Mary Chancement Webbel - Recome webster Personal Webbel 1333 Recome 1333 Rec				The state of the s			
Motor Chinoment Motor Chin				The state of the s			
More Dahament				The state of the s			
Motor Emperiment		Vehicle - Revenue vehicles		10333 Hampton Roads Transit	0	33	33
Motor Carbonement Vehicle - Remova whiches Paralizati Vehicle 1000 133 13 13 13 13 13							
Motor Enhancement Verlick - Remone whites				The state of the s			
Moze Tablecament Verlich - Fernent weithinds Fernant Verlich Fernant weithinds 100 13 13 13 13 13 13 1							
Motor Francement Webbis - Florense without Paratranct Vebbis 1000 Courty of television 0 13 13 13 13 13 13 13							
Miller Frankreimert Webbie - Revenue webbies Paratransit Vebbies 1909 Country of counter 1 1 1 1 1 1 1 1 1							
Minor Enhancement Verbic Ferente welniche Perstranch Verbiche 1020 Courty of Loudeum 0 3 3 1 1 1 1 1 1 1 1			Paratransit Vehicles	10209 County of Loudoun	0	33	33
Most Frahesement Welce- Beverus whelche Most Frahesement whelche Most Frahesement whelche Secretary wh							
Moter Frahementer Werder - Beverane whelster Werder - Beverane Fallites Werder - Beverane Whelster Werder - Beverane Fallites Wer							
Minor Enhancement Weinice - Revenue weinkole Minor Charlesement Weinice - Revenue weinkole Ligarismis Rui Nerlice							
Minor Enhancement Werkele-Revenue-websides Bis-Beltert/Costenue-Facilities Facility Construction - Perking Werkele-Revenue-websides Bis-Beltert/Costenue-Facilities Facility Construction - Perking Websides Werkele-Revenue-websides Websides W							
Minor Enhancement Vehicle-Revenue-vehicles Dipartion Ban Affeide 1939							
Moor Enhancement Vehicle - Recents vehicles Expansion Bay/Petrick 1923 A JAM7, Inc. 0 29 29 29 29 29 29 29							
Minor Enhancement	Minor Enhancement	Vehicle - Revenue vehicles	Expansion Bus/Vehicle	9954 Greensville County	0	29	
Moor Enhancement Verlick - Poerwas weholds Eparamon Ban/Weinde 10324 AUMT, Ir.C. 0 29 29 29 29 29 29 29							
Minor Finalmenterner							
Minor Fahracement Weisider - Benema wehleds Epsandon but/Vehilde 1000 Stry of Herizonburg popt of Pask Transportation 0 29 28 28 28 28 28 28 28							
Minor Finhammers Bus Shelters/Customer Facilities Facility Construction - Parking 1006 MVTC - Fairfax County 0 25 25 15 15 15 15 15 15							
Minor Inhancement							
Minor Enhancement Technology - Operations Rider Support Hardware - Fare Collection 10033 Hampton Rodos Transt 0 25 25 25 25 25 25 25	Minor Enhancement	Technology - Operations		10072 Blacksburg Transit	0	25	
Moor Enhancement	Minor Enhancement						
Moor Enhancement							
Moor Enhancement							
Minor Enhancement							
Minor Enhancement Technology - Operations Rider Support Hardware - TIS/Communicati 10031 Williamsburg Area Transit Authority 0 24 24 24 24 24 24 24							
Minor Enhancement Technology - Operations Rider Support Hardwarer - TSC-Communicati 10004 NTC - Fairfax County 0 24 24 24 24 24 24 24	Minor Enhancement	Technology - Operations		10031 Williamsburg Area Transit Authority	0	24	
Minor Enhancement Technology - Operations Rider Support Hardware - TSC-Communicati 1,0072 Blackshurg Transft 0 24 24							
Minor Enhancement Technology - Operations Rider Support Hardware - ITX/Communicati 1006 City of Hardronoburg Dept. of Public Transportation 0 24 24							
Minor Enhancement							
Minor Enhancement Technology - Operations Rider Support Hardware - ITS/Communicati 10324 AJANT, Inc. 0 24 24 24 24 24 24 24							
Minor Enhancement Maintenance equipment & parts Maintenance Maintenance Maintenance Maintenance Maintenance Maintenance Maintena							
Monor Enhancement Admin/Maintenance equipment & parts Maintenance Materials 10246 Farmville Area Bus 0 24 24 24 24 24 24 24	Minor Enhancement	Technology - Operations	Rider Support Hardware - ITS/Communicati	10324 JAUNT, Inc.	0	24	24
Minor Enhancement Technology - Operations Minor Enhancement Technology - Operations Minor Enhancement Maintenance equipment & parts Software Purchase - Vehicle Maintenance Maintenance equipment & parts Software Purchase - Vehicle Maintenance Maintenance equipment & parts Software Purchase - Vehicle Maintenance Maintenance equipment & parts Software Purchase - Vehicle Maintenance Maintenance equipment & parts Software Purchase - Vehicle Maintenance Maintenance equipment & parts Software Purchase - Vehicle Maintenance Vehicle - Revenue vehicles Purchase - Vondor Vehicles Logical Manor Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station Logida Department More Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station Logida Department More Enhancement Bus Shetters/Customer Facilities Engineering Service - Fueling Station Logida Daville Transit System Logida Department Bus Shetters/Customer Facilities Engineering Service - Fueling Station Logida Daville Transit System Logida Department Bus Shetters/Customer Facilities Wayfinding Adis - Signage Logida Daville Transit System Logida Davill					-		
Minor Enhancement Mystem Infrastructure Stafflith provement More Enhancement System Infrastructure Facility inprovement Maintenance equipment & parts More Enhancement Technology - Operations Software Purchase - Vehicle Maintenance Technology - Operations More Enhancement More Enhancement More Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station More Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station More Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station More Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station More Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station More Enhancement Admin/Maintenance Facilities Unifore Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage Wayfinding Aids - Signage More Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage Wayfinding Aids					-		
Minor Enhancement Maintenance equipment & parts Software Purchase - Vehicle Maintenance (1033) Hampton Roads Transit 0 22 22 22 22 22 22 22 24 Minor Enhancement Technology - Operations Software Purchase - Vehicle Maintenance (1033) Hampton Roads Transit 0 22 22 22 22 24 Minor Enhancement Vehicle Revenue whitels Purchase Support Vehicles 1024 AUNT, Inc. 0 18 18 18 18 18 18 18 18 18 18 18 18 18							
Minor Enhancement Technology - Operations Minor Enhancement Technology - Operations More Financement Technology - Operations More Financement							
Minor Enhancement			Software Purchase - Vehicle Maintenance				22
Minor Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station Minor Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station 1094 Danville Transit System 0 18 18 18 18 18 18 18 18 18 18 18 18 18 1			Software Purchase - On board	10272 PRTC			
Minor Enhancement Admin/Maintenance Facilities Engineering Service - Fueling Station 10031 Williamsburg Area Transit Authority 0 18 18 18 Minor Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage 10930 City of Suffolk 0 16 16 16 16 16 16 16 16 16 16 16 16 16							
Minor Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage 10390 City of Suffolk 0 16 16 16 16 16 16 16 16 16 16 16 16 16							
Minor Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage 10094 Damille Transit System 0 16 16 16 16 16 16 16 16 16 16 16 16 16							
Minor Enhancement Bus Shelters/Customer Facilities Wayfinding Aids - Signage 10094 Danville Transit System 0 16 16 16 16 16 16 16 16 16 16 16 16 16							
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation 1015 Bay Aging 0 16 16 16 16 16 16 16 16 16 16 16 16 16				10094 Danville Transit System			16
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation 1032 Blacksburg Transit 0 16 16 16 16 16 16 16 16 16 16 16 16 16			Wayfinding Aids - Signage				
Minor Enhancement Minor Enhanc							
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation 10094 Danville Transit System 0 16 16 16 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation 9954 Greensville Country 0 16 16 16 16 Minor Enhancement Rethnology - Operations Rider Support Hardware - Safety 10047 NVTC - VRE 0 16 16 16 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation 10174 Pulaski Area Transit 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10060 City of Petersburg 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10060 City of Petersburg 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10094 Danville Transit System 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10094 Danville Transit System 0 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10094 Danville Transit Company 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10047 NVTC - VRE 0 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10047 NVTC - VRE 0 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10097 Drown Of Blackstone Area Bus System 0 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10079 Town Of Blackstone Area Bus System 0 16 16 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10322 Greater Richmond Transit Company 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10322 Greater Richmond Transit Company 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10324 Greater Richmond Transit Company 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10324 Greater Richmond Transit Company 0 15 15 15 Minor Enhancement Bus Shelters/Customer							
Minor Enhancement Bus Shelters/Customer Facilities Rider Support Hardware - Safety 10047 NVTC - VRE 0 16 16 16 16 16 16 16 16 16 16 16 16 16							
Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10174 Pulaski Area Transit 0 16 16 16 16 16 16 16 16 16 16 16 16 16							
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation 10174 Pulaski Area Transit 0 16 16 16 16 16 16 16 16 16 16 16 16 16							
Minor Enhancement Technology - Operations Rider Support Hardware - Safety 1009 City of Petersburg 0 16 16 16 16 16 16 16 16 16 16 16 16 16		Bus Shelters/Customer Facilities	Wayfinding Aids - Signage	10174 Pulaski Area Transit	0	16	16
Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10342 Greater Richmond Transit Company 0 16 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10342 Greater Richmond Transit Company 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10047 NVTC - VRE 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10077 DWN Off Blackstone/ Blackstone Area Bus System 0 16 16 16 Minor Enhancement Bus Shelters/Customer Facilities Graphics Package for Vehicles 10072 Blacksburg Transit 0 16 16 16 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10322 Greater Richmond Transit Company 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Artifigent County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Artifigent County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Grid of Alexandria 0 15 15 15 Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0							
Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10322 Greater Richmond Transit Company 0 16 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10047 NVTC - VRE 0 16 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10027 PRTC 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10027 PRTC 0 0 16 16 16 Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10079 Town Of Blackstone/ Blackstone Area Bus System 0 16 16 16 Minor Enhancement Bus Shelters/Customer Facilities Graphics Package for Vehicles 10072 Blacksburg Transit 0 16 16 16 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10322 Greater Richmond Transit Company 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arlington County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arlington County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arlington County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10043 NVTC - City of Alexandria 0 15 15 15 Minor Enhancement Perchanger - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0							
Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10272 PRTC 0 16 16 16 16 16 16 16 16 16 16 16 16 16							
Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10072 PRTC Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10079 Town Of Blackstone Area Bus System 0 16 16 Minor Enhancement Bus Shelters/Customer Facilities Graphics Package for Vehicles 10072 Blacksburg Transit 0 16 16 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10322 Greater Richmond Transit Company 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 19954 Greensville County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arington County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Gity of Alexandria 0 15 15 Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 On the State of Good Repair Vehicle - Revenue vehic							
Minor Enhancement Technology - Operations Rider Support Hardware - Safety 10079 Town Of Blackstone/ Blackstone Area Bus System 0 16 16 16 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10322 Greater Richmond Transit Company 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arlington County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arlington County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arlington County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10043 NVTC - City of Alexandria 0 15 15 15 Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0							
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10322 Greater Richmond Transit Company 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Artington County 0 15 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Grup of Alexandria 0 15 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Grup of Alexandria 0 15 15 15 15 Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 15 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				10079 Town Of Blackstone/ Blackstone Area Bus System			16
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Artifiquent County 0 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Gity of Alexandria 0 15 15 15 Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Bus Shelters/Customer Facilities	Graphics Package for Vehicles	10072 Blacksburg Transit			
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 9954 Greensville County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arlington County 0 15 15 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 100321 NVTC - City of Alexandria 0 15 15 15 Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 5 15 15 15 15 15 15 15 15 15 15 15 15 1							
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10321 NVTC - Arlington County 0 15 15 Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10043 NVTC - City of Alexandria 0 15 15 15 Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0							
Minor Enhancement Bus Shelters/Customer Facilities Bus Shelter Installation - Components 10043 NVTC - City of Alexandria 0 15 15 15 Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0							
Minor Enhancement Technology - Operations Admin and Operations Software Renewal 10322 Greater Richmond Transit Company 0 12 12 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0							
State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0							
State of Good Repair Vehicle - Revenue vehicles Purchase Replacement Bus 10043 NVTC - City of Alexandria 0 0 0		Vehicle - Revenue vehicles	Purchase Replacement Bus	10043 NVTC - City of Alexandria	0		
					0		
					0	0	0

Project Type	Project Category (Primary	Project Category (Secondary)	Application #	Grantee	Asset Condition SCORE	Quality Impact SCORE	TECHNICAL SCORE
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10043 NVTC - Cit	ty of Alexandria	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10070 Town of E	Bluefield-Graham Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10031 Williamsb	ourg Area Transit Authority	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10031 Williamsb	ourg Area Transit Authority	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10333 Hampton	Roads Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10025 AASC / Fo	our County Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10134 RADAR-Ro	ockbridge	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10246 Farmville	Area Bus	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10347 Virginia R	legional Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10347 Virginia R	legional Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Replacement Bus	10072 Blacksbur	rg Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Expansion Bus/Vehicle	10293 Fredericks	sburg Regional Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Expansion Bus/Vehicle	10293 Fredericks	sburg Regional Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Expansion Bus/Vehicle	10293 Fredericks	sburg Regional Transit	0	0	0
State of Good Repair	Vehicle - Revenue vehicles	Purchase Support Vehicles	10347 Virginia R	legional Transit	0	0	0